Department of Physics

Safety Inspection

Level:	Inspection Team:
JA 4,3,2,1	AC,JG
JA 8,7,6	AC,JG,JR
Col 3,2,1	AC,JG
Laser:	ТА
High Voltage:	MH,JR

General Comments:

Good practice was found in many areas:-

- Illumines floor tape used in laser room
- Safe Operating Procedures (SOP) displayed on gas bottle
- Coshh forms on display
- Gas manifold inspection and check list on display

Areas that need work:-

- Portable appliances not within the test period therefore should be removed from use and re-tested.
- Compressed gas warning notices not displayed at entrance doors.

Room	General	Laser	High Voltage
JAL8			
832	Trailing cables, PAT out of		
	date, replace gas warning sign		
	on door, gas regulator with no		
	date, fire extinguisher out of		
	date, broken 13A plug		
	connected to fume cupboard		
827	Gas regulator out of date, PAT		
	out of date, needs tidying,		
	remove redundant telescope -		
	hazard		
JAL7			
715	PAT out of date, HVAC vents		
	dirty		
713	Trailing cables		
732			
729			
705	3ph cable left lying-remove,		
	very warm, trailing cables,		
	remove redundant laser		
	interlock system, ceiling tiles		
	to be replaced. PAT out of		
	date, store Acetone in a safe		

	place, cosh forms not visible	
JAL6		
615	PAT out of date, HVAC grill	
	dirty	
626	HVAC grill hanging down, PAT	
	out of date, items storage	
	above cupboards – please	
620	keep clear	
628	Ceiling tile down, check 3PH	
	bench plug if not in use	
620-	remove.	
628a	Label the contents of the acid	
	cupboard and fridge, dispose	
602	of empty chemical bottles	
602	fume cupboard dirty, PAT out	
	of date, ceiling tiles to be	
(0)	replaced, two ceiling lights out	
602a	Good practise- Illumines floor tape, Safe Operating	
	Procedures (SOP) on Gas	
	bottle, use of cable protectors,	
	gas bottles highlighted on	
	laboratory door. PAT out of	
	date	
608	Replace gas warning sign on	
000	door, PAT out of date, ceiling	
	tile to be replaced, flammable	
	chemical stored on floor next	
	to exit	
611b		
611	PAT out of date, Good practise	
	- cable protectors used.	
611b	Require a sign highlighting a	
	delay at the start and stop	
	functions of the fume	
	cupboard (F/C) M/K/FC/0014,	
	have the isolation switch for	
	the F/C moved to a suitable	
	place, label contents of	
	chemical fridge, PAT out of	
	date, replace gas warning sign	
	on door	
JAL4		
413b	Light diffuser cracked	
410	Require new glass bin, sink	
	cracked	
JAL3		
315	Flooring bubbled - due to be	
	replaced in Jan15, chemical	
	cupboard left open,	
	Good practise – Coshh forms	
	displayed, eyewash required	
315a	Display Coshh forms next to	

	Fridge, No drain at fixed	
	eyewash station	
315b	Floor service duct loose	
310a	PAT out of date, trailing cables	
310	Area warm, PAT out of date	
322	Chemicals not stored	
318	Old oil drums to be disposed,	
	tidy	
206	No gas warning sign on door	
207	Tidy, remove boxes on HVAC	
	ducting,	
202a	Move fume cupboard isolation	
	switch to a suitable place, PAT	
	out of date, Good practise –	
	Coshh forms displayed.	
JAL1		
111f	PAT out of date, Aircon units	
	vents need cleaned	
111a		
111b	Acetone left out, Good	
	practise – Gas manifold	
	inspection and check list on	
	display	
111c		
COL3		
308	Fire extinguishers on floor out	
	of date, PAT out of date,	
	cabling from table to be raised	
	to more suitable height	
306		
307	Good practise – SOP visible	
321	Good practise – RA and Coshh	
	forms visible	
320	Tidy under desks	
211		
203	No gas warning sign on door,	
	window broken, lights out, no	
	dust extraction on grinder, Bay	
	1 cable under table re-route,	
	Bay 3 tidy cables, Bay 4, earth	
	cable protection re-route	
103	No date on gas regulator, No	
	gas warning sign on door,	
	remove table from fire exit	
	corridor, remove boards from	
	electrical distribution board	
L		· I